

General Environmental Incident Summary

Incident: 3745

Date/Time Notice: 5/4/2015

DEM Incident No:

Responsible Party: Steve Lessard

Date Incident: 5/4/2015

Time Incident:

Duration:

10 minutes

County: Walsh

Twp: 157

Rng: 52

Sec: 14

Qtr:

Lat: 48.41249

Long: -97.29966

Method: Interpolation from map

Location Description: spill came down 157th Ave NE on County Rd through Grafton to the Simplot elevator. spill was about 2" wide on paved road very small.

Submitted By: Sandi Washek

Affiliation:

Address: 918 E Dlvide Ave

City: Bismarck

State: ND

Zip:

Received By:

Contact Person:

15274 Ctry Rd 11

Grafton, ND 58237

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: valve on nosel opened

Description of Released Contaminant: Sonalan

Volume Spilled: 5.00 gallons

Ag Related: Yes

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Valve on hose nozzle vibrated open and cause some of the product to come out of the tank.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil in Simplot yard - clean up and contained, paved streets were cleaned

Action Taken or Planned:

Closed the nozzle valve and put in in more secure area of the tank so if it happens again the product will stay in the tank. Also cleaned up all the impacted soil in the Simplot yard. The Grafton Fire Dept. clean up the product on the city & county streets. Farmer will apply the waste product to his crop land.

Wastes Disposal Location: On farmers crop land

Agencies Involved:

Updates

Date: 5/6/2015 **Status:** Reviewed - No Action Required

Author: Washek, Sandi

Updated Volume: 5.00 gallons

Notes:

Contacted the farmer. Simplot personnel and county emergency manager all on site. Simplot has cleaned up the area of impact on the gravel in company yard by using Floor Dry and removing soil (less than a 5-gallon bucket of soil and product removed). The county fire dept cleaned the streets where a small trail of product was released. The product was dry by time of removal, and the department was just removing the dye left by the product on the street. All has been cleaned up and disposed of. No further followup required.